


AAMA/WDMA/CSA 101/I.S.2/A440-08 TEST REPORT

Rendered to:

MI WINDOWS AND DOORS, INC.

SERIES/MODEL: 1650



Title Summary of Results

A.L.I

AAMA AEBTIEICATION PROGRAM



MI Windows & Doors, LLC P.O. Box 370 Gratz, PA 17030-0370

Attn: Rick Sawdey

The product described below is hereby approved for listing in the next issue of the AAMA Certified Products Directory. The approval is based on successful completion of tests, and the reporting to the Administrator of the results of tests, accompanied by related drawings, by an AAMA Accredited Laboratory.



Rendered to:

MI WINDOWS AND DOORS, INC. P.O. Box 370 650 West Market Street Gratz, Pennsylvania 17030-0370

Report No.: A0295.01-109-47

Test Date: 04/28/10

Report Date: 05/17/10

Test Record Retention Date: 04/28/14

Project Summars: Architectural Testing Inc. was contracted by MI Windows and Doors Inc.




Tes	st Specimen Description: (Continued)
	<u></u>
•	P ⁻
1. ,	
·	
	-
	Claring Dataile: The unit was plazed with 7/8" thick insulating glass constructed from two
	Closing Details: The unit was plazed with 7/8" thick insulating glass constructed from two
-	
-	
-	
-	
-	
-	



Test Results: (Continued)

5.3.5 Forced Entry Resistance per ASTM F 588
·
·
·
•
·
·
·
•
Type: D Grade: 10
Disassembly Test No entry No entry
5.3.6.2 Thermoplastic Corner Weld Test Meets as stated Meets as stated
Optional Performance
4.3.2.1 Water Penetration Resistance per ASTM E 547 360 Pa (7.52 psf) No leakage No leakage





Per the client, this product is also labeled under the following names:

1555

Bryn Mawr III

1650 HP


New Castle III


3450

List of Official Observers:

<u>Name</u> <u>Company</u>

Rick Sawdey MI Windows and Doors, Inc.







Revision Log

<u>Rev. #</u>	<u>Date</u>	Page(s)	Revision(s)
0	05/17/10	N/A	Original report issue



Appendix A

Alteration Addendum

Alteration #1: Date - 04/28/10

Cause for alteration - Failed 7.52 psf water test

Remedial action taken - Resealed glazing leg at bottom rail



Appendix B

Test Equipment

Instrument		Manufacturer	Asset #
	Control Donal	Architectural Testing Inc	 MI_1





Appendix C

Drawings

Note: Complete drawings packet on file with Architectural Testing, Inc.